

# Inspection Photos

October 10, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 323977

Location Name: GIBSON GULCH UNIT-66S91W/29NENW

Inspection Document #: 702800812

Garfield County, CO

NENW Section 29 T6S R91W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: GIBSON GULCH UNIT-66S91W/29NENW  
Location ID: 323977



**Photo 1.** Photo taken from the north shows an overview of the Location.



## Inspection Photos

Location Name: GIBSON GULCH UNIT-66S91W/29NENW

Location ID: 323977



**Photo 2.** Photo taken to the southwest of the separator shows erosion degradation occurring at a stormwater BMP.



**Photo 3.** Refer to Photo 2 comment.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800812



Inspection Photos  
Location Name: GIBSON GULCH UNIT-66S91W/29NENW  
Location ID: 323977



**Photo 4.** Photo taken from the west shows production areas.





Inspection Photos  
Location Name: GIBSON GULCH UNIT-66S91W/29NENW  
Location ID: 323977



**Photo 5.** Photo taken from the east shows production areas.



**Photo 6.** Photo taken from the south shows production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800812



## Inspection Photos

Location Name: GIBSON GULCH UNIT-66S91W/29NENW

Location ID: 323977



**Photo 7.** Photo taken from the north shows the northern interim area colonized by perennial grasses.



**Photo 8.** Refer to Photo 7 comment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800812