

# Inspection Photos

October 10, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335339/311596

Location Name: GIBSON GULCH UNIT-66S91W/29NENW

Inspection Document #: 702800815

Garfield County, CO

SWSW Section 20 T6S R91W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: GIBSON GULCH UNIT-66S91W/29NENW  
Location ID: 335339/311596



**Photo 1.** Photo taken from the south shows production areas.



**Photo 2.** Photo taken from the north shows production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800815



## Inspection Photos

Location Name: GIBSON GULCH UNIT-66S91W/29NENW

Location ID: 335339/311596



**Photo 3.** Photo shows the southwestern interim area. Perennial grasses are established, but sparse.



**Photo 4.** Photo shows the northern interim area. Perennial grasses are established, but sparse.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800815



## Inspection Photos

Location Name: GIBSON GULCH UNIT-66S91W/29NENW

Location ID: 335339/311596



**Photo 5.** Photo taken from the east shows rill erosion occurring on the eastern slopes of the location.



**Photo 6.** Refer to Photo 5 comment.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800815



Inspection Photos

Location Name: GIBSON GULCH UNIT-66S91W/29NENW

Location ID: 335339/311596



**Photo 7.** Photo taken from the east shows rill erosion occurring on the eastern slopes of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800815