

Inspection Photos
Location Name: Lind 24-1
Location ID: 311876



Photo 1 – Wellhead



Photo 2 – Wellhead

Inspection Photos
Location Name: Lind 24-1
Location ID: 311876




Photo 3 – Wellhead – Stained Soil



Photo 4 – Pumping Unit – Looking East

Inspection Photos
Location Name: Lind 24-1
Location ID: 311876



Photo 5 – Pumping Unit – Looking West



Photo 6 – Gas Engine House – Stained Soil

Inspection Photos
Location Name: Lind 24-1
Location ID: 311876



Photo 7 – Inside Gas Engine House – Stained Soil



Photo 8 – Inside Gas Engine House

Inspection Photos
Location Name: Lind 24-1
Location ID: 311876



Photo 9 – Inside Gas Engine House – Stained Soil



Photo 10 – Tank Battery Sign

Inspection Photos
Location Name: Lind 24-1
Location ID: 311876



Photo 11 – Tank Battery



Photo 12 – Tank Battery

Inspection Photos
Location Name: Lind 24-1
Location ID: 311876



Photo 13 – Separator



Photo 14 – Separator

Inspection Photos
Location Name: Lind 24-1
Location ID: 311876



Photo 15 – Unused Tubing Strings



Photo 16 – Propane Tank

Inspection Photos
Location Name: Lind 24-1
Location ID: 311876



Photo 17 – Tank Labels



Photo 18 – Tank Labels