

Inspection Photos  
Location Name: Henderson #1  
Location ID: 331730




Photo 1 – Wellhead



Photo 2 – Tank Battery

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 3 – Unmarked Risers**



**Photo 4 – Unused Heater Treater, Gas Meter Shed and Concrete Pad**

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 5 – Pumping Unit – Unused Rods**



**Photo 6 – Wellhead**

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 7 – Unused Containment**



**Photo 8 – Unused Tubing**

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 9 – Heater Treater**



**Photo 10 – Unmarked Riser**

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 11 – Unmarked Risers**