

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #1 Inadequate Berm/ Unused Frac Tank



Photo #2 Trash



Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #3 Trash



Photo #4 Unused Gas Meter Runs

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #5 Unused Gas Meter Runs



Photo #6 Unused Gas Meter Runs

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #7 Removed Totes



Photo #8 Removed trash

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #9 Removed Trash



Photo #10 Removed Trash

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #11 Removed Unused Equipment



Photo #12 Removed Unused Equipment

Inspection Photos
Location Name: Helton 5-63-27
Location ID: 434121



Photo #11 Removed Trash



Photo #12 Removed Unused Equipment

