

Inspection Photos
Location Name: WPF III-66N64W/18NWNE
Location #: 323559



Photo #1
WPF III A18-2 (05-123-13195) Wellsite
Temporarily Abandoned | TA
*Weeds need cleared
prior photo*



Photo #2
WPF III A18-2 Wellsite
Temporarily Abandoned | TA
Weeds have been mitigated

Inspection Photos
Location Name: WPF III-66N64W/18NWNE
Location #: 323559



Photo #3
WPF III A18-2 Battery site
Inactive / Shut-down
Formerly served:
WPF III A 18-7, Carlson A18-17;
Plugged & Abandoned | PA
prior photo