



Inspection Photos
location: 416625
Inspection
Date:10/18/2022

All Photos taken
by Kris Neidel

Photo #2 spilled chemicals on pad surface. (There is NO "Photo #1)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection
Photos
location:
416625
Inspection
Date:10/18
/2022

All Photos
taken by
Kris Neidel

Photo #3 Stored hoses, leaking fluid. Pile of soil behind hoses is the stockpiled excavated material to build pad. North side of pad





Inspection
Photos
location: 416625
Inspection
Date:10/18/2022

All Photos taken
by Kris Neidel

Photo #4 spilled chemicals on pad surface being tracked and compacted and mixed with gravel.



Inspection
Photos
location: 416625
Inspection
Date:10/18/2022

All Photos taken
by Kris Neidel

Photo #5 Close up of stained soil being compacted and tracked. Note: trash in photo. Trash was observed everywhere around the pad. The inspector noted they could not walk five feet without seeing another piece of trash.



Inspection
Photos
location: 416625
Inspection
Date:10/18/2022

All Photos taken
by Kris Neidel

Photo #6 stained pad surface on north side of pad. Note: removal of stockpiled pad soil and trash.





Inspection
Photos
location: 416625
Inspection
Date:10/18/2022

All Photos taken
by Kris Neidel

Photo #7 Forground, Pile of unknown material. Piles of other material in the background.





Inspection
Photos
location: 416625
Inspection Date:
10/18/2022

All Photos taken
by Kris Neidel

Photo #8 plastic liner where above ground tanks were removed. Note: chemicals mixing with other fluids and being tracked around location. Note: tear in liner material





Inspection
Photos
location: 416625
Inspection
Date:10/18/2022

All Photos taken
by Kris Neidel

Photo #9 plastic liner where above ground tanks were removed. Note: chemicals mixing with other fluids and being tracked around location.



Inspection
Photos
location:
416625
Inspection
Date:
10/18/2022

All Photos
taken by Kris
Neidel

Photo #10 pump with water on ground. It has not rained in last week.



Inspection
Photos
location: 416625
Inspection
Date:10/18/2022

All Photos taken
by Kris Neidel

Photo #11 cuttings storage bin. Appears was overtopped with cutting. Note fluid on ground. It has not rained in the last week.



Inspection Photos
location: 416625
Inspection
Date:10/18/2022

All Photos taken by Kris
Neidel

**Photo #11 stormwater retention pond on north-west side of pad. Hose passing off pad is connected to an adjacent pad 1.3 miles away.
Note: trash in stormwater pond; cardboard, plastic, bottle**



Inspection
Photos
location: 416625
Inspection
Date:10/18/2022

All Photos taken
by Kris Neidel

Photo #12 hose mentioned in Photo #11 leaving the location.



Inspection
Photos
location: 416625
Inspection Date:
10/18/2022

All Photos taken
by Kris Neidel

Photo #13 close up of stormwater pond to left of photo. Note: more trash.





Inspection Photos
Location: 416625
Inspection
Date:10/18/2022

All Photos taken
by Kris Neidel

Photo #14 Storage tote and drums. Note: stained soil



Inspection
Photos
location: 416625
Inspection
Date:10/18/2022

All Photos taken
by Kris Neidel

Photo #15 Trash pile? Unknown Fluid on pad surface.





Inspection
Photos
location: 416625
Inspection
Date:10/18/2022

All Photos taken
by Kris Neidel

Photo #16 Bin to left of photo is cuttings bin. Stained soil, puddle



Inspection
Photos
location:
416625
Inspection
Date:
10/18/2022

All Photos
taken by Kris
Neidel

Photo #17 cuttings bin with loader parked in front. Note: fluid that is greater than de minimis amount of moisture pooling out of bin.



Inspection
Photos
location:
416625
Inspection
Date:
10/18/2022

All Photos
taken by Kris
Neidel

Photo #18 cuttings bin to right of photo. Stained soil on pad, spilled chemical





Inspection Photos
location: 416625
Inspection Date:
10/18/2022
All Photos taken by
Kris Neidel

Photo #19 overview of location and well. Crews were removing Above ground tanks from location.