

Inspection Photos

October 11, 2022

Operator: Mull Drilling Company Inc - #61250

Location ID: 313088

Location Name: STATE AVALANCHE-612N92W/24SESE

Inspection Document #: 702800840

Moffat County, CO

SESE Section 24 T12N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: STATE AVALANCHE-612N92W/24SESE

Location ID: 313088



Photo 1. Photo taken from the south shows the reclaimed access road. The entire Location has been fenced to exclude livestock.



Photo 2. Photo taken from the south shows the vegetation community on the reclaimed access road. Seeded western wheatgrass is common as well as a variety of annual undesirable plant species and noxious weeds. Note dense cover of mulch smothering vegetation in some areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800840

Inspection Photos

Location Name: STATE AVALANCHE-612N92W/24SESE

Location ID: 313088



Photo 3. Photo shows an example of an area with relatively good perennial establishment. Perennial grasses are the yellowish-tan plant. Weeds are darker brown. Note also dense mulch.



Photo 4. Photo shows an example of an area with relatively poor perennial establishment. Perennial grasses are the yellowish-tan plant. Weeds are darker brown.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800840

Inspection Photos

Location Name: STATE AVALANCHE-612N92W/24SESE

Location ID: 313088



Photo 5. Photo taken from the center of the Location shows the start of disturbed area vegetation monitoring transect #1.



Photo 6. Photo taken from the center of the Location shows the ground surface at the start of disturbed area vegetation monitoring transect #1.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800840

Inspection Photos

Location Name: STATE AVALANCHE-612N92W/24SESE

Location ID: 313088



Photo 7. Photo taken from the center of the Location shows the end of disturbed area vegetation monitoring transect #1.



Photo 8. Photo taken from the center of the Location shows the ground surface at the end of disturbed area vegetation monitoring transect #1.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800840

Inspection Photos

Location Name: STATE AVALANCHE-612N92W/24SESE

Location ID: 313088



Photo 9. Photo taken to the north of the Location shows the start of reference area vegetation monitoring transect #1.



Photo 10. Photo taken to the north of the Location shows the ground surface at the start of reference area vegetation monitoring transect #1.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800840

Inspection Photos

Location Name: STATE AVALANCHE-612N92W/24SESE

Location ID: 313088



Photo 11. Photo taken to the north of the Location shows the end of reference area vegetation monitoring transect #1.



Photo 12. Photo taken to the north of the Location shows the ground surface at the end of reference area vegetation monitoring transect #1.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800840