

Inspection Photos

October 20, 2022

Operator: EOG Resources Inc - #27742

Location ID: 313220

Location Name: BAKERS PEAK-611N91W/13SWNE

Inspection Document #: 702800845

Moffat County, CO

SWNE Section 13 T11N R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BAKERS PEAK-611N91W/13SWNE
Location ID: 313220



Photo 1. Photo taken to the west shows the reclaimed access road. Photo shows an area with good perennial establishment, lacking annual undesirable plant species and noxious weeds.



Photo 2. Photo taken to the west shows the reclaimed access road. Photo shows an area with good perennial establishment, however, a patch of Scotch thistle (List B Noxious) is present.

Inspection Photos
Location Name: BAKERS PEAK-611N91W/13SWNE
Location ID: 313220



Photo 3. Photo shows the easternmost portion of the access road at the Location entrance. The area is densely covered in annual undesirable plant species (tall tumblemustard) and noxious weeds (cheatgrass) with little to no perennial establishment.



Photo 4. Photo taken from the south shows an overview of the reclaimed Location. Overall perennial species are very well established, however portions of the Location lack perennial species and are dominated by weeds. Weedy species are the lighter tan color, while perennial grasses are the darker, orange-tan color. Note dense patch of cheatgrass in foreground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800845

Inspection Photos

Location Name: BAKERS PEAK-611N91W/13SWNE

Location ID: 313220



Photo 5. Photo taken from the northeast shows the largest and most continuous area lacking perennial species and dominated by annual undesirable plant species and noxious weeds.



Photo 6. Photo shows the area at the northeast of the Locations is densely colonized by cheatgrass and tall tumblemustard.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800845

Inspection Photos
Location Name: BAKERS PEAK-611N91W/13SWNE
Location ID: 313220



Photo 7. Photo shows an example of a Scotch thistle (List B Noxious) rosette on Location.



Photo 8. Photo shows an example of a bull thistle (List B Noxious) plant which has gone to seed and is acting as a seed source.

Inspection Photos

Location Name: BAKERS PEAK-611N91W/13SWNE

Location ID: 313220



Photo 9. Photo shows an example of an area with excellent perennial establishment at the west of the Location.



Photo 10. Photo shows an example of an area with excellent perennial establishment at the center of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800845

Inspection Photos
Location Name: BAKERS PEAK-611N91W/13SWNE
Location ID: 313220



Photo 11. Photo shows an example trash/debris on Location.



Photo 12. Photo shows an example trash/debris on Location.

Inspection Photos

Location Name: BAKERS PEAK-611N91W/13SWNE

Location ID: 313220



Photo 13. Photo taken to the south shows the reference area vegetation community is native rangeland. The herbaceous understory is densely colonized by native perennial grasses and forbs. Noxious weeds are absent.



Photo 14. Photo shows a close-up of the vegetation community in Photo 13. The grass in the photo is Sandberg bluegrass (native, perennial bunchgrass).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800845