

Organic Energy Company Ellgen 11-10-1 Location # 424294



location



location

**Organic Energy Company
Ellgen 11-10-1
Location # 424294**



location



location

Organic Energy Company
Ellgen 11-10-1
Location # 424294



Staining



Staining

Organic Energy Company
Ellgen 11-10-1
Location # 424294



Labels fading



Labels fading

Organic Energy Company
Ellgen 11-10-1
Location # 424294



Labels fading



Cap/plug missing

**Organic Energy Company
Ellgen 11-10-1
Location # 424294**



Stored equipment



location

Organic Energy Company
Ellgen 11-10-1
Location # 424294



Unmarked tank



Unmarked tank

Organic Energy Company
Ellgen 11-10-1
Location # 424294



Staining



Debris

Organic Energy Company
Ellgen 11-10-1
Location # 424294




Staining




Staining

Organic Energy Company
Ellgen 11-10-1
Location # 424294



Staining



Staining

**Organic Energy Company
Ellgen 11-10-1
Location # 424294**



Staining



Debris

Organic Energy Company
Ellgen 11-10-1
Location # 424294



Debris



Debris

**Organic Energy Company
Ellgen 11-10-1
Location # 424294**



Oct 18, 2022 at 10:58:39 AM
40.497452, -107.597943 ±4.77m
COGCC

Debris/stored equipment




Oct 18, 2022 at 10:58:47 AM
40.497452, -107.597943 ±4.77m
COGCC

Debris/stored equipment



Organic Energy Company
Ellgen 11-10-1
Location # 424294



Staining



Cellar full of fluid