

Inspection Photos

October 20, 2022

Operator: HRM Resources LLC - #10273

Location ID: 313096

Location Name: SAND HILLS FED-612N91W/20NESE

Inspection Document #: 702800852

Moffat County, CO

NESE Section 20 T12N R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: SAND HILLS FED-612N91W/20NESE

Location ID: 313096



Photo 1. Photo taken to the west of the Location shows the unreclaimed Fee portion of the access road. Soil are bare and compacted in tracks. Cheatgrass (List C Noxious) is common.



Photo 2. Photo taken to the west of the Location shows the Federal portion of the access road which has been reclaimed. Portions of the road are poorly vegetated. Bare ground and annual weeds are common. Vehicle traffic appears to be impacting reclamation and causing the formation of a two-track.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800852

Inspection Photos
Location Name: SAND HILLS FED-612N91W/20NESE
Location ID: 313096



Photo 3. Photo taken from the west shows an overview of the reclaimed Location.



Inspection Photos
Location Name: SAND HILLS FED-612N91W/20NESE
Location ID: 313096



Photo 4. Photo shows an example of areas dominated by noxious weeds. Cheatgrass is common and dominant in some areas. Scotch thistle (List B Noxious) (circled) is widespread and very numerous.



Photo 5. Refer to Photo 4 comment.

Inspection Photos
Location Name: SAND HILLS FED-612N91W/20NESE
Location ID: 313096



Photo 6. Photo shows an example of areas with poor perennial establishment, dominated by cheatgrass.



Photo 7. Refer to Photo 6 comment.

Inspection Photos
Location Name: SAND HILLS FED-612N91W/20NESE
Location ID: 313096



Photo 8. Photo taken from the north shows a portion of the Location with good perennial establishment.

Inspection Photos
Location Name: SAND HILLS FED-612N91W/20NESE
Location ID: 313096



Photo 9. Photo taken to the south of the Location shows the reference area vegetation community. Levels of cheatgrass are low. Scotch thistle is absent.

