

Inspection Photos
Location Name: Amen #1
Location ID: 319144



Photo 1: Wellhead Sign



Photo 2: Stained soil

Inspection Photos
Location Name: Amen #1
Location ID: 319144



Photo 3: Stained soil



Photo 4: Stained soil

Inspection Photos
Location Name: Amen #1
Location ID: 319144



Colorado Oil & Gas Conservation Commission
40.3941, -104.94265, 1472.5m, 287°
Oct 25, 2022 1:28:43 PM

Photo 5: Waste in open container



Colorado Oil & Gas Conservation Commission
40.39406, -104.94262, 1472.0m, 338°
Oct 25, 2022 1:29:03 PM

Photo 6: Unused/disconnected equipment, weeds

Inspection Photos
Location Name: Amen #1
Location ID: 319144



Photo 7: Tank not grounded, no berm surrounding tank



Photo 8: Weeds