

# Final Reclamation and Stormwater Inspection

October 19, 2022

Operator: VERDAD RESOURCES LLC #10651

Location ID: 437015

Inspection Document #: 697504303

Weld County, CO

SWSE Section 26 T8N R60W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Hemberger/7-26-8-60 PAD  
Location ID: 437015



**Photo 1.** Photo taken from the former entrance of location, facing North. Photo illustrates the establishment of annual, weedy Kochia.



**Photo 2.** Photo taken from the central location, facing South. Photo illustrates the establishment of mostly introduced grass species and Kochia with some natives.



Inspection Photos  
Location Name: Hemberger/7-26-8-60 PAD  
Location ID: 437015



**Photo 3.** Photo taken from the central location, facing West.  
See comments under Photo 2.



**Photo 4.** Photo taken from the central location, facing North.  
See comments under Photo 2.



Inspection Photos  
Location Name: Hemberger/7-26-8-60 PAD  
Location ID: 437015




**Photo 5.** Photo taken from the northern location, facing West. Photo illustrates an area of annual, weedy Kochia establishment.



**Photo 6.** Photo taken from the northern location, facing North. See comments under Photo 5.



Inspection Photos  
Location Name: Hemberger/7-26-8-60 PAD  
Location ID: 437015



**Photo 7.** Reference photo taken south of the location, facing East. Photo illustrates native grass species and no introduced grass species were observed.

