

Inspection Photos  
Location Name: Stark 19-13#1  
Location ID: 320379



Photo#1 Production Tanks/**Corrective Action Weeds**



Photo#2 Separator/**Corrective Action Weeds**

Inspection Photos  
Location Name: Stark 19-13#1  
Location ID: 320379



Photo#3 Pumpjack/**Corrective Action:Weeds**