


Inspection Photogs
Location Name: Kelsall 33-7 4-1
Location ID: 424701




IMG 01
Well sign



IMG 02
Location overview



IMG 03
Weeds at produced water tank



IMG 04
Weeds on berms



IMG 05
Weeds on berms



IMG 06
Weeds at 4-2 pump jack



IMG 07
Weeds at 4-1 and 4-2 pump jack




IMG 08
Tank capacity not labeled.



IMG 09

Tank capacity not labeled.




IMG 10

Impacted material



IMG 11

Impacted material at 4-4 wellhead



IMG 12

Impacted material at 4-2 wellhead



IMG 13
Impacted material at 4-1 wellhead



IMG 14
Fragments of previous drive belt are trash.



IMG 15

Panel is trash/unused equipment



IMG 16

Water bottle is trash



IMG 17
Rag is trash



IMG 18
Diminished berm height.