

**Inspection Photogs**  
**Location Name: Heikkinen 1-10**  
**Location ID: 325560**



**IMG 01**  
**Well sign**



**IMG 02**  
**Location overview**



**IMG 03**  
**Location overview**



**IMG 04**  
**Weeds at wellhead**



**IMG 05**

**Weeds at produced water tank and berms**



**IMG 06**

**Weeds at produced water tank and berms**



**IMG 07**  
**Weeds at separator**



**IMG 08**  
**Weeds at tanks and berms**



**IMG 09**

**Weeds at tanks and berms**



**IMG 10**

**Unused equipment**



**IMG 11**  
**Tank sign is deteriorated**



**IMG 12**  
**Tank sign is deteriorating, capacity not listed**