

P6 Lateral Near GR12 Well Pad Spill/Release

Spill/Release ID: 480397

Inspection Date: October 25, 2022




Photo #1 - 2019 COGCC GIS Online Map Viewer aerial photo depicting reported Spill/Release location (circled in black).



Inspection Photos
P6 Lateral near GR12 Well Pad Spill/Release
Spill/Release ID: 480397
Inspection Date: October 25, 2022



Photo #2 – Overview of reported Spill/Release location, looking northeast.

Photo #3 – Overview of reported Spill/Release location, looking west.

