

Inspection Photos

A7E Pipeline Leak

Spill/Release ID: 482257

Inspection Date: October 25, 2022



Photo #1 - 2019 COGCC GIS Online Map Viewer aerial photo depicting reported Spill/Release location (circled in black).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
A7E Pipeline Leak
Spill/Release ID: 482257
Inspection Date: October 25, 2022



Photo #2 – View of Remediation Project area from north, looking southwest. Note damaged straw wattle in foreground.



Photo #3 – Valve can on north side of Remediation Project area.



Inspection Photos
A7E Pipeline Leak
Spill/Release ID: 482257
Inspection Date: October 25, 2022



Photo #4 – Vegetation has been removed on west end of Remediation Project area.



Photo #5 – Loose straw on south side of Remediation Project area.



Inspection Photos
A7E Pipeline Leak
Spill/Release ID: 482257
Inspection Date: October 25, 2022



Photo #6 – Monitoring well in Remediation Project area.



Photo #7 – PVC risers in Remediation Project area.



Inspection Photos
A7E Pipeline Leak
Spill/Release ID: 482257
Inspection Date: October 25, 2022



Photo #8 – Four monitoring well risers were observed in Remediation Project area on inspection date. Note damaged straw wattle in foreground.



Photo #9 – Straw wattle in roadside ditch located south of Remediation Project area.

