

Final Reclamation and Stormwater Inspection

October 19, 2022

Operator: RED HAWK PETROLEUM LLC - #10503

Location ID: 426701

Inspection Document #: 697504313

Weld County, CO

Lot 3 Section 1 T7N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 1. Photo taken from the entrance of location, facing South. Photo illustrates no desirable vegetation has established throughout the access road portion.



Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 2. Photo taken from the northern location, facing East. Photo illustrates the establishment of desirable vegetation.

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 3. Photo taken from the northern location, facing Southeast. Photo illustrates the southeastern location has no desirable vegetation establishment.

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 4. Photo taken from the northern location, facing Southwest. Photo illustrates the western location has no desirable vegetation establishment.