

Comment: Landowner appears to be storing trailer on location, located ~60' from wellhead (IMG 03). No surface owner variance on file.

Corrective Action: Remove stored equipment per rule 606.a **Date:** 01/24/2023



Picture from INC showing the land owners trailer sitting on the side of location.



Land owner has removed trailer from location. Picture taken on 10-31-2022 by Steve Walters.