

Inspection Photos

API: 073-06349

Operator: RUNNING FOXES PETROLEUM INC

Inspection Date: 10/25/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06349 - Date: 10/25/2022

Inspection Photos



Photo 1. Drone aerial photo facing south down toward the location. There are areas of the location that have not adequately established vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06349 - Date: 10/25/2022

Inspection Photos



Photo 2. Facing north at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06349 - Date: 10/25/2022

Inspection Photos



Photo 3. Facing west at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06349 - Date: 10/25/2022

Inspection Photos



Photo 4. Facing south at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06349 - Date: 10/25/2022

Inspection Photos



Photo 5. Facing east at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06349 - Date: 10/25/2022

Inspection Photos



Photo 6. View of ground cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06349 - Date: 10/25/2022

Inspection Photos



Photo 7. Facing south at the beginning of the transect at the location.



Photo 8. Facing north at the end of the transect at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06349 - Date: 10/25/2022

Inspection Photos



Photo 9. Facing northeast at the beginning of the transect at the undisturbed reference area.



Photo 10. Facing southwest at the end of the transect at the undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06349 - Date: 10/25/2022

