

Inspection Photogs


Location Name: Lemon J 1
Location ID: 325590



IMG 01
Well sign



IMG 02
Location overview



IMG 03

Stormwater channel on NE corner



IMG 04

Stormwater channel continues across location



IMG 05

Stormwater channel continues



IMG 06

Erosion channel adjacent to access road



IMG 07

Ruts have become erosion channels on access road



IMG 08

Erosion channel on west side fill slope



IMG 09

Berm not maintained, sediment migrating onto location, near produced water tank



IMG 10

Berm not maintained, sediment migrating onto location, near produced water tank