

Inspection Photos

October 31, 2022

Operator: Argali Exploration Company - #3975

Location ID: 313043

Location Name: OKES-68N90W/6SWNW

Inspection Document #: 702800881

Moffat County, CO

SWNW Section 6 T8N R90W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: OKES-68N90W/6SWNW
Location ID: 313043



Photo 1. Photo taken from the southwest shows an overview of the Location.



Inspection Photos
Location Name: OKES-68N90W/6SWNW
Location ID: 313043



Photo 2. Photo taken from the northwest shows a decommissioned produced water tank facility. Decommissioned facilities require site investigation and remediation followed by interim reclamation after compliance with 915-1 standards. Photo also shows waste/debris.



Photo 3. Photo taken from the northwest shows a pipe remaining at the produced water tank facility. Pipe must be removed. Photo also shows waste/debris.

Inspection Photos
Location Name: OKES-68N90W/6SWNW
Location ID: 313043



Photo 4. Photo taken from the southeast of the Location shows a decommissioned partially buried vessel facility. Decommissioned facilities require site investigation and remediation followed by interim reclamation after compliance with 915-1 standards.



Inspection Photos
Location Name: OKES-68N90W/6SWNW
Location ID: 313043



Photo 5. Photo taken from the northeast shows equipment.



Photo 6. Photo taken from the northeast. The methanol tank secondary containment lacks wildlife protection BMPs. Tank label is faded and illegible.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800881

Inspection Photos
Location Name: OKES-68N90W/6SWNW
Location ID: 313043




Photo 7. Photo shows the wellhead. Wellhead sign does not comply with Rule 605.d.



Inspection Photos
Location Name: OKES-68N90W/6SWNW
Location ID: 313043



Photo 8. Photo shows an example of Canada thistle (List B Noxious) found occasionally throughout the Location.



Photo 9. Photo shows interim areas at the south of the Location are well vegetated with perennial grasses. Red circle indicates a List B noxious thistle.