

Inspection Photogs
Location Name: Ignacio 33-8 1
Location ID: 325160



IMG 01
Well sign



IMG 02
Location overview



IMG 03

Ruts on access road



IMG 04

Ruts on access road



IMG 05

Gas releasing from fittings



IMG 06

Ruts on location