

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/02/2022

Submitted Date:

11/04/2022

Document Number:

707600492

FIELD INSPECTION FORM

Loc ID 306587 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289852	WELL	PR	06/01/2021	OW	123-24953	SHOEMAKER A 12-7	PR

General Comment:

This is a WELL inspection.
Well(s): 1: Producing | PR.
Battery: Active.

Centralized Battery serves 4 Location IDs (306584, 306585, 306586, 306587).
(Well(s): 3: Producing | PR ; 1: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #707600490 and/or Location ID #306584 for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.501549,-104.491986
Comment:	Centralized Battery serves 4 Location IDs (306584, 306585, 306586, 306587). (Well(s): 3: Producing PR ; 1: Temporarily Abandoned TA).				
Corrective Action:					Date:

Paint

Condition:

Other (Content):

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date: <input style="width:100px;" type="text"/>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: <input style="width:100px;" type="text"/>

Flaring:

Type		
Comment:		
Corrective Action:		Date: <input style="width:100px;" type="text"/>

Inspected Facilities

Facility ID: 289852 Type: WELL API Number: 123-24953 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/30/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 11/02/2022 at approximately 15:57 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: SHOEMAKER A-66N64W/12SWNE Location ID: 306587 Well Name(s): Shoemaker A 12-7. API: 123-24953. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 4 Location IDs (306584, 306585, 306586, 306587). (Well(s): 3: Producing PR ; 1: Temporarily Abandoned TA).</p> <p>Refer to Field Inspection Report doc. #707600490 and/or Location ID #306584 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/04/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707600493	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5906310