

Comment: Unused electrical equipment at pump control panels (IMG 03), unused metal panel at wellhead (IMG 04).

Corrective Action: All unused equipment must be returned to use or stored off location per rule 606.



Pictures from the INC showing the unused electrical equipment and metal panel.



Picture 1 showing that the unused electrical equipment has been removed.

Picture 2 is showing the metal panel has been replaced into the belt guard. It was the bottom piece of the belt guard that was not replaced after a belt replacement.

Picture 3 is showing the ground where the metal panel was prior to being reinstalled.