


Inspection Photogs  
Location Name: Warren Davis C 2  
Location ID: 306921



IMG 01  
Well sign




IMG 02  
Location overview





**IMG 03**  
**Produced water release**



**IMG 04**  
**Produced water release**





**IMG 05**

**Unused fuel container.**