

Inspection Photos

November 7, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335295

Location Name: RMV-66S94W/20SWSE

Inspection Document #: 702800897

Garfield County, CO

SWSE Section 20 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: RMV-66S94W/20SWSE
Location ID: 335295



Photo 1. Photo shows production areas at the east of the Location.



Photo 2. Photo shows production areas at the west of the Location.

Inspection Photos
Location Name: RMV-66S94W/20SWSE
Location ID: 335295



Photo 3. Photo shows eastern interim areas dominated by perennial grasses with occasional shrubs.



Photo 4. Photo shows northern interim areas dominated by perennial grasses with occasional shrubs.

Location ID: 335295

50° NE



Photo 5. Photo shows lack of stabilization of the working pad surface.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800897