

Final Reclamation Inspection

September 3rd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 332828

Inspection Document #: 701900642

NWSW Section 20 T4N R65W

Corey McDonough
Reclamation Contractor, COGCC



CO L O R A D O

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Peschel 13-20
Location ID: 332828



Photo 1. 2021 aerial imagery of the well pad, access road and tank battery.

Inspection Photos
Location Name: Peschel 13-20
Location ID: 332828




Photo 2. Overview photo of the well pad, access road and reference area taken from directly above the well pad using a drone. Note: well pad and reference area appear consistent with the adjacent reference area.

Inspection Photos
Location Name: Peschel 13-20
Location ID: 332828



Photo 3. Overview photo of the tank battery taken at ground level from the eastern edge facing north.



Inspection Photos
Location Name: Peschel 13-20
Location ID: 332828



Photo 4. Cardinal photos taken from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Peschel 13-20
Location ID: 332828



Photo 5. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: sign falls within an unmanaged area along the edge of the agriculture access road. No signs of oil or gas operations observed.