

# Inspection Photos

November 7, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335742

Location Name: CLOUGH-66S94W/16NENW

Inspection Document #: 702800909

Garfield County, CO

NENW Section 16 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: CLOUGH-66S94W/16NENW

Location ID: 335742



**Photo 1.** Photo shows an overview of the northern portion of the Location.



**Photo 2.** Photo shows an overview of the southern portion of the Location.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800909

Inspection Photos  
Location Name: CLOUGH-66S94W/16NENW  
Location ID: 335742



Photo 3. Photo shows northern production areas.



## Inspection Photos

Location Name: CLOUGH-66S94W/16NENW

Location ID: 335742



**Photo 4.** Photo shows the northern interim areas of the Location are dominated by perennial grasses. Note also tamarisk (List B Noxious).



**Photo 5.** Photo shows taken from the east shows berms stabilized by perennial vegetation.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800909