

Inspection Photos

November 7, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335453

Location Name: LANGSTAFF-66S94W/16NWSW

Inspection Document #: 702800911

Garfield County, CO

NWSW Section 16 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LANGSTAFF-66S94W/16NWSW
Location ID: 335453



Photo 1. Photo shows an overview of the production area.

Inspection Photos
Location Name: LANGSTAFF-66S94W/16NWSW
Location ID: 335453



Photo 2. Photo shows tamarisk (List B Noxious) at the north of the Location.



Inspection Photos

Location Name: LANGSTAFF-66S94W/16NWSW

Location ID: 335453



Photo 3. Photo shows northern interim areas. Note tamarisk.



Photo 4. Photo shows western interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800911

Inspection Photos
Location Name: LANGSTAFF-66S94W/16NWSW
Location ID: 335453



Photo 5. Photo shows stormwater BMPs at the west of the Location showing some signs of degradation; stormwater cutting beneath rocks, sediment traps approaching capacity.



Inspection Photos
Location Name: LANGSTAFF-66S94W/16NWSW
Location ID: 335453



Photo 6. Photo shows stormwater BMPs at the west of the Location showing some signs of degradation; stormwater cutting through rocks, sediment traps approaching capacity.

