

Inspection Photos

November 7, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 324148

Location Name: LANGSTAFF-66S94W/16SWSW

Inspection Document #: 702800915

Garfield County, CO

SWSW Section 16 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: LANGSTAFF-66S94W/16SWSW

Location ID: 324148




Photo 1. Photo shows an overview of the Location. Note pad showing lack of stabilization/compaction.



Photo 2. Photo shows an overview of the Location. Note pad showing lack of stabilization/compaction.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800915

Inspection Photos
Location Name: LANGSTAFF-66S94W/16SWSW
Location ID: 324148



Photo 3. Note pad showing lack of pad stabilization/compaction.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800915

Inspection Photos

Location Name: LANGSTAFF-66S94W/16SWSW

Location ID: 324148




Photo 4. Photo shows interim areas at the east of the Location vegetated with perennial grasses and shrubs.



Photo 5. Photo shows interim areas at the east of the Location vegetated with perennial grasses and shrubs.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800915