


Inspection Photos
Location Name: Muegge Hand 41-31#1
Location ID:319894



Photo#1 Production Tank

Photo#2 Separator and Gas Meter

Inspection Photos
Location Name: Muegge Hand 41-31#1
Location ID:319894



Photo#3 Wellhead

Photo#4 Labels on Produced Water tank illegible