

# Inspection Photos

November 8, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335613

Location Name: FEDERAL-66S94W/11NWNW

Inspection Document #: 702800931

Garfield County, CO

NWNW Section 11 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: FEDERAL-66S94W/11NWNW  
Location ID: 335613



**Photo 1.** Photo shows an overview of the northern (well area) production pad. Note unused, unreclaimed area ~0.25 acres.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800931



Inspection Photos  
Location Name: FEDERAL-66S94W/11NWNW  
Location ID: 335613



**Photo 2.** Photo shows production areas to the south.





Inspection Photos  
Location Name: FEDERAL-66S94W/11NWNW  
Location ID: 335613



**Photo 3.** Photo taken from the western edge of the northern production area shows bull thistle.



**Photo 4.** Photo taken from the northwestern edge of the northern production area shows Scotch thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800931



Inspection Photos  
Location Name: FEDERAL-66S94W/11NWNW  
Location ID: 335613



**Photo 5.** Photo shows well API 045-11929 where bubbles were observed in the well cellar



**Photo 6.** Photo shows one of three unmarked anchors observed.



Inspection Photos  
Location Name: FEDERAL-66S94W/11NWNW  
Location ID: 335613



**Photo 7.** Photo shows the interim area to the south is dominated by native perennial grasses (bluebunch wheatgrass).



**Photo 8.** Photo shows the interim area to the northeast is dominated by native perennial grasses (bluebunch wheatgrass) and shrubs (fourwing saltbush).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800931