

Comment: Produced water tank has no tank sign/placard (IMG 06 and IMG 07).

Corrective Action: Install sign to comply with Rule 605.h. **Date:** 12/07/2022



Picture from INC of missing tank sign.



Pictures showing the new tank sign on the tank.

Comment: Trough, 2" pipe. and pipe attachment at 2-17 wellhead are not in use. Unused wire fencing at produced water tank (IMG 04).

Corrective Action: All unused equipment must be returned to use or stored off location per rule 606. **Date:** 11/15/2022



Picture from INC showing the unused equipment on location.



Pictures showing that unused equipment has been removed from location.

Picture 1 shows that the trough and pipe have been removed.

Picture 2 shows that the unused fence has been removed.

Comment: Weeds at produced water tank (IMG 05).

Corrective Action: Ensure within 25' of wellhead, tanks, and separators are free of combustible material per rule 610.k. **Date:** 11/15/2022.



Picture from INC showing the weeds around the tank.



Pictures showing that the weeds have been removed from around the tank.