

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER-67S93W /12SWSE

Location ID: 334650



Photo #8369 From entrance to location.



Photo #8370 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER-67S93W /12SWSE

Location ID: 334650



Photo #8371 From entrance to location.



Photo #8372 Chemical tank missing required information.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER-67S93W /12SWSE

Location ID: 334650



Photo #8068 from inspection #699805063 conducted on 10/14/22.