

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /33SESW

Location ID: 334862



Photo #8427 From entrance to location.



Photo #8428 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /33SESW

Location ID: 334862



Photo #8429 Multiple loadlines open ended.



Photo #8431 Multiple loadlines open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /33SESW

Location ID: 334862



Photo #8432 Undesirable plant species in tank containment



Photo #8433 Undesirable plant species in tank containment