

COLORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION FORM



00416523

| | | | |
|---|-------------------------|---|---|
| <input checked="" type="checkbox"/> UNSATISFACTORY INSPECTION | | 1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100 | |
| <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION | | | |
| API No. 05- <u>001 - 05029</u> | | LEASE NAME: <u>M. Noonen #1</u> | |
| LOCATION: <u>SWNW 24-35-59W</u> | | OPERATOR: <u>Walsh</u> | |
| DATE: <u>8-7-95</u> | | INSPECTOR: <u>Ed Binkley 8/24/95</u> | |
| Insp. Type: <u>ID</u> | Insp. Status: <u>TA</u> | PA: Y N | Pass/Fail: P <u>F</u> Viol.: Y <u>N</u> NOV: Y <u>N</u> |

| INSPECTION ITEM | COMMENTS | INPUT |
|---------------------------|------------------------------------|-------|
| Well ID Signs | | |
| Pits (Reserve/Production) | | |
| Fences | | |
| Tank Battery Equipment | <u>1-300, VHT, Shut in on 27/8</u> | |
| Fire Walls/Berms/Dikes | | |
| General Housekeeping | | |
| Spills (Oil/Water) | | |
| Bradenhead | | |
| Drilling Well/Workover | | |
| Surface Rehabilitation | | |
| Miscellaneous | <u>MIT required per Rule 324b.</u> | |

| |
|---|
| CORRECTIVE ACTION REQUIRED: <u>Mechanical integrity test per 324b.</u> |
| Date Corrective Action Required By: <u>9-30-95</u> Date Remedied: |

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.