

# **FREMONT ENVIRONMENTAL INC.**

September 29, 2022

Mr. Jason Davidson  
PDC Energy  
4000 Burlington Ave  
Evans, CO 80620

Subject:       **Soil Vapor Monitoring Points - Abandonment Letter**  
Former Edstrom 24-8 Wellhead  
SESW Sec 8, T1S, R67W  
Adams County, Colorado  
Fremont Project No. C022-129  
Facility #203472, API 05-001-09031

Dear Mr. Davidson:

As you requested, Fremont Environmental Inc. (Fremont) personnel removed four soil vapor monitoring points that were present adjacent to the former Edstrom 24-8 wellhead. These 1/4" diameter tubing vapor points were approximately three feet deep and completed at the surface with 2" diameter PVC protective covers.

Fremont personnel removed the protective covers, tubing and the bentonite seal material from each of the four vapor points. Each vapor point was then backfilled with surrounding soil. Photos of the vapor points and abandonment work are attached.

Please contact me at (303) 956-8714 if you require any additional information.

Fremont appreciates the opportunity to provide this service.

Sincerely,  
**FREMONT ENVIRONMENTAL INC.**



Paul V. Henehan, P.E.  
Senior Consultant

Attachment - Photo Log

## Photo Log



**Description:**

#1 - Looking North at Four Soil Vapor Monitoring Points with KPK Wells in Background

## Photo Log



**Description:**

#2 - Overhead View of Soil Vapor Monitoring Point; Note 1/4" Tubing



## Photo Log



**Description:**

#3 - Soil Vapor Monitoring Point with Protective Cover Removed

## Photo Log



**Description:**

#4 - Monitoring Points had a Bentonite Seal



## Photo Log



**Description:**

#5 - Bentonite Seal around Tubing which was Approximately 3 Feet Long

## Photo Log



**Description:**

#6 - Four Dismantled Soil Vapor Points



## Photo Log



**Description:**

#7 - Backfilled Monitoring Points

## Photo Log



**Description:**

#8 - Looking Northwest at Soil Vapor Monitoring Points Prior to Abandonment