

# Inspection Photos

November 16, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 425554

Location Name: Kline /21-23

Inspection Document #: 702800943

Moffat County, CO

NENW Section 23 T7N R91W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Kline /21-23  
Location ID: 425554



**Photo 1.** Photo taken from the Location entrance shows signage with incorrect Operator information.



**Photo 2.** Photo shows Russian olive, a CO List B Noxious Weed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800943



Inspection Photos  
Location Name: Kline /21-23  
Location ID: 425554



**Photo 3.** Photo taken from the east of the location shows cut slopes are bare and exposed. Rill erosion is evident.



**Photo 4.** Photo taken from the southwest of the location shows cut slopes are bare and exposed. Rill erosion is evident.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800943