

Inspection Photos

November 16, 2022

Operator: Beeman Oil & Gas LLC - #7125

Location ID: 428927

Location Name: Bulldog /5-31H-790

Inspection Document #: 702800948

Moffat County, CO

Lot 6 Section 5 T7N R90W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Bulldog /5-31H-790
Location ID: 428927



Photo 1. Photo shows an overview of the location. Note unused and unmarked risers.



Inspection Photos
Location Name: Bulldog /5-31H-790
Location ID: 428927



Photo 2. Photo shows the well sign lacks the well API number. See below for close-up.



Photo 3. Photo shows a close-up of Photo 2.

Inspection Photos
Location Name: Bulldog /5-31H-790
Location ID: 428927



Photo 4. Photo shows the tank battery sign lacks the well API number.



Inspection Photos
Location Name: Bulldog /5-31H-790
Location ID: 428927



Photo 5. Photo shows unused risers at the south of the location.



Photo 6. Photo shows an unused riser adjacent to the tank battery.



Inspection Photos
Location Name: Bulldog /5-31H-790
Location ID: 428927



Photo 7. Photo taken from the west of the Location shows missing/insufficient wildlife protection BMPs on the secondary containment stock tank.



Inspection Photos
Location Name: Bulldog /5-31H-790
Location ID: 428927



Photo 8. Photo taken from the shed at the southwest of the Location shows soil staining throughout the area. Photo also shows unused equipment stored within the shed.



Photo 9. Photo taken from the shed at the southwest of the Location shows a bucket containing oily fluid. Small mammal observed dead within the bucket.

Inspection Photos
Location Name: Bulldog /5-31H-790
Location ID: 428927



Photo 10. Photo shows an example of bull thistle, a CO List B Noxious weed.



Photo 11. Photo shows an example of Canada thistle, a CO List B Noxious weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800948

Inspection Photos
Location Name: Bulldog /5-31H-790
Location ID: 428927



Photo 12. Photo taken from the northeast of the Location shows areas not needed for production operations where interim reclamation has not been performed. Interim reclamation is required.



Inspection Photos
Location Name: Bulldog /5-31H-790
Location ID: 428927



Photo 13. Photos taken from the cut slopes to the west of the Location shows widespread rill erosion occurring on slopes. Although snow cover obscures the slope, rills remain. There is no evidence the slope has been stabilized per previous corrective actions.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800948