

Inspection Photos  
Location Name: Bullard#2  
Location ID:319955



Photo#1 Production Tank and Produced Water Tank

Photo#2 Separator/Gas Meter

Inspection Photos  
Location Name: Bullard#2  
Location ID:319955



**Photo#3 Corrective Action Mechanical Conditions**

**Photo#4 Wellhead  
Corrective Action/Fence In Disrepair**