



00401214

## WELL SITE INSPECTION FORM

LOCATION SW NW 23-35-58W  
OPERATOR NATIONAL CO-OP  
WELL NAME GILLETTE #1

FIELD ROMAN NOSE NORTH  
COUNTY ADAMS  
PERMIT # \_\_\_\_\_

## DATE OF INSPECTION DURING DRILLING: \_\_\_\_\_

RIG \_\_\_\_\_ SURFACE CASING: \_\_\_\_\_ DEPTH: \_\_\_\_\_  
BOP'S \_\_\_\_\_ RETURNS: \_\_\_\_\_ WOC: \_\_\_\_\_  
CONTACT \_\_\_\_\_ CMT VOL: \_\_\_\_\_  
ADEQUATE AQUIFER PROTECTION? \_\_\_\_\_  
COMMENTS \_\_\_\_\_

## DATE OF INSPECTION AFTER COMPLETION: \_\_\_\_\_

FRACED: YES \_\_\_\_\_ NO \_\_\_\_\_ PRODUCTION STRING: \_\_\_\_\_  
WATER DISPOSAL: PITS \_\_\_\_\_, INJECTED \_\_\_\_\_, COMMERCIAL \_\_\_\_\_, UNKNOWN \_\_\_\_\_, N.A. \_\_\_\_\_  
PITS: PERMIT Y \_\_\_\_\_ N \_\_\_\_\_, SKIM TANK Y \_\_\_\_\_ N \_\_\_\_\_, DIMENSIONS \_\_\_\_\_  
LEASE SIGN: YES \_\_\_\_\_ NO \_\_\_\_\_ TANK ID: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ FENCED: YES \_\_\_\_\_ NO \_\_\_\_\_  
SURFACE EQUIPMENT: \_\_\_\_\_  
COMMENTS: \_\_\_\_\_

DATE OF P&A INSPECTION 9/16/86

PITS BACKFILLED: YES ☒ NO ☐ SURFACE RECLAIMED: YES ☒ NO ☐  
HOLE MARKER: YES ☐ NO ☒ SITE CLEAN: YES ☒ NO ☐  
BOND RELEASE OK: YES ☒ NO ☐ LANDOWNER RELEASE: YES ☐ NO ☐  
COMMENTS: WHEAT FIELD STUBBLE

## DATE OF SAFETY INSPECTION \_\_\_\_\_

COMMENTS: \_\_\_\_\_

INSPECTOR SSK

API No. 05-001-08531

P&A Inspected: Yes ☒ No ☐