

## Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16NWNW

Location #: 302508



**Photo #1**

**Bashor State AA 16-04 (123-29253) Wellsite**

**Temporarily Abandoned | TA**

**CA: Weeds need cleared**

*prior photo*



**Photo #2**

**Bashor State AA 16-04 Wellsite**

**Temporarily Abandoned | TA**

**CA: Resolved. Weeds NOW mitigated.**

*Operator provided photo: FIRR*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name:** BASHOR STATE AA-66N63W/16NWNW

**Location #:** 302508



### Photo #3

**Bashor State AA 16-5, 16-3, 16-04, 16-6, 16-12,  
16-19, 16-20** Battery site

**Abandoned: ALL Equipment Removed**  
*prior photo*