

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16NENW

Location #: 302516



Photo #1

Bashor State AA 16-19 (123-29261) Wellsite

Temporarily Abandoned | TA

CA: Weeds need cleared

prior photo



Photo #2

Bashor State AA 16-19 Wellsite

Temporarily Abandoned | TA

CA: Resolved. Weeds NOW mitigated.

Operator provided photo: FIRR



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16NENW

Location #: 302516



Photo #3

**Bashor State AA 16-5, 16-3, 16-04, 16-6, 16-12,
16-19, 16-20** Battery site

Abandoned: ALL Equipment Removed
prior photo