

# Inspection Photos

November 23, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 414152

Location Name: Rulison/17M Pad

Inspection Document #: 702800960

Garfield County, CO

SWSW Section 17 T7S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Rulison/17M Pad  
Location ID: 414152



**Photo 1.** Photo shows an overview of the southernmost production area, including interim areas.



Inspection Photos  
Location Name: Rulison/17M Pad  
Location ID: 414152



**Photo 2.** Photo shows an overview of the northernmost production area.



**Photo 3.** Photo shows an overview of the central production area. Photo also shows degradation to pad surface.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800960



Inspection Photos  
Location Name: Rulison/17M Pad  
Location ID: 414152



**Photo 4.** Photo shows degradation to pad surface at the entrance to the well production pad.



Inspection Photos  
Location Name: Rulison/17M Pad  
Location ID: 414152



**Photo 5.** Photo shows portions of the interim area which appear to be dominated by annual undesirable plant species and cheatgrass (List C Noxious).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800960



## Inspection Photos

Location Name: Rulison/17M Pad

Location ID: 414152



**Photo 6.** Photo shows an example of houndstongue (List B Noxious) in the southern interim area.



**Photo 7.** Photo shows an example of bull thistle (List B Noxious) in the southern production area.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800960