

Inspection Photos

API: 071-07696

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/28/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07696 | Date: 11/28/2022

Inspection Photos



Photo 1. Facing south along the access road. This area of the road was graded and repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07696 | Date: 11/28/2022

Inspection Photos



Photo 2. The eroded area of the road was repaired however, loose soils are not stabilized and will erode. There is no outlet protection installed at the culvert shown at red arrow.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07696 | Date: 11/28/2022

Inspection Photos



Photo 3. Facing back where the road was repaired. Loose soils along the embankment are susceptible to erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07696 | Date: 11/28/2022

Inspection Photos



Photo 4. Facing southeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07696 | Date: 11/28/2022