

Inspection Photos

Location Name: CAERUS PICEANCE LLC GASAWAY (SHERFFIELD)-66S99W /17NESW

Location ID: 322471



Photo #8514 From entrance to location.



Photo #8516 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GASAWAY (SHERFFIELD)-66S99W /17NESW

Location ID: 322471



Photo #8518 Location lacks stabilization.



Photo #8520 Insufficient tracking controls at entrance to location.