

Inspection Photos

API: 043-06141

Operator: JAVERNICK OIL

Inspection Date: 12/1/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06141 | Date: 12/1/2022

Inspection Photos



Photo 1. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 12/1/2022

Inspection Photos




Photo 2. The panels at the well head have fallen over including the well sign.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 12/1/2022

Inspection Photos



Photo 3. There is an unused tank that still remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 12/1/2022