

Inspection Photos
Location Name: WALCKER USX/AB01-08P
Location #: 416142



Photo #1

Walcker USX AB01-08P (123-31301) Wellsite
Temporarily Abandoned | TA



Photo #2

Walcker USX AB 01-07P, 01-05P, 01-08P Battery site
Active ; Equipment documented: Loc. # 415995
Formerly served:
Walcker USX AB 01-06P ;
Plugged & Abandoned | PA